

Other minor typographical errors are being corrected in the specification on columns 1, 5 and 16 as well as in the drawings Figs. 5, 6, 15, 16 and 21. The specification in column 15 has clarified what is shown in step 407(b).

In the claims, all of the original Claims, 1-15, are retained without change. New Claims 16-39 are submitted. These include the broadcast technique for an ARP request in an ATM system. Most of the language corresponds to some of the language utilized in Claims 1-15.

All additional material has been indicated by the use of underlines. All deleted material has been indicated by the use of brackets. All corrections to the drawings have been noted in red.

These remarks are being submitted to assist the Examiner in further understanding the reasons for the present reissue.

Any fee due with this paper, not fully covered by an enclosed check, may be charged to Deposit Account 08-1634.

Respectfully submitted,

Samson Helfgott
Reg. No. 23,072

Helfgott & Karas, P.C.
Empire State Building
New York, New York 10118
(212) 643-5000
Docket No: 12.689A

SH/gau/16501

09427945 102699